SUPPLEMENTAL EXAMINER'S AMENDMENT

The application has been amended as follows:

The numbering of claims is not in accordance with 37 CFR 1.126 which requires the original numbering of the claims to be preserved throughout the prosecution. When new claims are presented, they must be numbered consecutively beginning with the number next following the highest numbered claims previously presented (whether entered or not).

Misnumbered claim 6, listed as the second (2nd) claim 6 which reads "The window of claim 4 wherein the seal element comprises a butyl adhesive." has been renumbered as claim 8.

Any inquiry concerning this communication or earlier communications from the examiner should be directed to BRYAN EPPES whose telephone number is (571)270-3109. The examiner can normally be reached on M-F; alt. Fri. off (7:30am-5pm EST.). If attempts to reach the examiner by telephone are unsuccessful, the examiner's supervisor, Richard Chilcot can be reached on (571) 272-6777. The fax phone number for the organization where this application or proceeding is assigned is 571-273-8300.

Information regarding the status of an application may be obtained from the Patent Application Information Retrieval (PAIR) system. Status information for published applications may be obtained from either Private PAIR or Public PAIR. Status information for unpublished applications is available through Private PAIR only. For more information about the PAIR system, see http://pair-direct.uspto.gov. Should you have questions on access to the Private PAIR system, contact the Electronic Business Center (EBC) at 866-217-9197 (toll-free). If you would like assistance from a USPTO Customer Service Representative or access to the automated information system, call 800-786-9199 (IN USA OR CANADA) or 571-272-1000.

/Richard E. Chilcot, Jr./

Application/Control Number: 10/537,399 Page 3

Art Unit: 3635

Supervisory Patent Examiner, Art Unit 3635

/B. E./

Examiner, Art Unit 3635